

# Charger Cup Selection Chart



Impact Part Number	Radio Models
<b>Motorola</b>	
MOT-1	GP300, P110, GP350, P1225/LS, LTS2000, GTX/LTR
MOT-2	HT750, HT1250LS, HT1550/LS/XLS, MTX850/LS, MTX950, MTX8250/LS, MTX9250, EX500, EX560, EX600, EX600XLS, GL200, PRO5150, PRO7150, PRO9150, PR860, Infinity P-1000, P1010
MOT-3	P040, P080, GP308, GP88S, CT150, CT250, CT450/LS, PRO3150
MOT-5/7	HT1000, MTX838, MTX1000, JT1000, MT1500, MT2000, MTS2000, MTX900, MTX9000, MTZ2000, MTX8000, MTXLS, XTS3000, XTS3500, XTS5000, PR1500, XTS1500, XTS2500, GP900
MOT-8	HT600, HT800, MT1000, P200, P210, MTX800
MOT-11	CP150, CP200/CP200d, PR400
MOT-12	VL130, BC120, CP125, AXV5100, AXU4100, GP2000 - Special Order Only
MOT-13	MAG ONE/BPR40, BC130, BC300
MOT-15	MOTO TRBO, XPR3300, XPR3350, XPR3550, XPR6300, XPR6350, XPR6380, XPR6500, XPR6550, XPR6580, XPR7000, XPR7350, XPR7500, XPR7550, RM Series, DP2400/2600, APX900, APX1000, APX3000, APX4000 <b>Battery Only:</b> PMMN4409 <i>Impact batteries do not currently provide battery conditioning equivalent to OEM Motorola IMPRES Chargers.</i>
MOT-18	Motorola CP185, CP100D
MOT-19	APX 6000, 7000, 8000 SPX 2200
<b>Kenwood</b>	
<b>Quick Tip:</b> More than one cup may apply to your radio so please compare your battery model before choosing cup.	
KEN-1	TK-190/290/390, TK-260/360, TK-270, TK-272G, TK-278, TK-280/380/480, TK-370, TK-372G, TK-2100/3100, TK-3101, TK-3130, TK-3131, TK-481, TK-5400, TH-K2AT <b>Battery Models:</b> KNB-14, KNB-15, KNB-16, KNB-17, KNB-17L, KNB-20, KNB-21, KNB-22, KNB-52
KEN-3	TK-2140/3140, TK-2160/3160, TK-2170/3170, TK-2360/3360, TK-3173, TH-072A, Nexedge NX220/320, NX-3300 <b>Battery Models:</b> KNB-24L, KNB-25A, KNB-26N, KNB-35L, KNB-40LC, KNB-55L, KNB-56N, KNB-57L, KNB-79
KEN-4	TK-2200/3200, TK-2202/3202, TK-2300/3300, TK-2302/3302, TK-2312/3312, TK-2402/3402/4402 <b>Battery Models:</b> KNB-29, KN-B30
KEN-5	TK-2180/3180, TK-2180MPT/3180MPT, TK-5210/5310/5410, TK-5220/5320, Nexedge NX200, NX210, NX300, NX410 <b>Battery Models:</b> KNB-31, KNB-32, KNB-33L, I.S. battery KNB-41NC, KNB-43L, KNB-47L, KNB-48L, KNB-49PL, KNB-50NC, KNB-54N, KNB-L1, KNB-L2, KNB-L3

## Questions About Our Charger Cups?

Contact us at **1-866-532-9005** | [sales@impactcomms.com](mailto:sales@impactcomms.com)

[ImpactComms.com](http://ImpactComms.com)

# Charger Cup Selection Chart



Impact Part Number	Radio Models
KEN-6	TK-2202/3202/4202, TK-2212/3212/4212, TK-2300/3300/4300, TK-2302/3302/4302, TK-2312/3312/4312, TK-2402/3402/4402, KNB-45, <b>Battery Models:</b> KNB-45L
<b>Icom</b>	
IC-2	F3GT/F4GT, F3GS/4GS, F21, F21S, F22, F30GT/40GT, F30G/F40G, F11 <b>Battery Models:</b> BP-195, BP-196, BP-208, BP-209, BP-210, <b>Not Supported:</b> BP-211
IC-4	F50/F50V, F60/F60V <b>Battery Models:</b> BP-227, BP-227FM
IC-5	F70DT/80DT, F70T/80T, F70DS/80DS, F70S/80S, F9011T/9021T, F9011S/9021S, F9011B/9021B <b>Battery Models:</b> BP-237, BP-253, BP-254
IC-6	F3001/4001 <b>Battery Models:</b> BP-264 <b>Not Supported:</b> BP-265, BP-269
<b>Vertex</b>	
<b>Quick Tip:</b> More than one cup may apply to your radio so please compare your battery model before choosing cup.	
MOT-15	VXD-720 Series APX 900, 1000, 3000, 4000
VY-1	VX-110, VX-150, VX-160, VX-180, VX-210, VX-400, VX-410, VX-414, VX-417, VX-420, VX-800, VXA12, VXA120, VXA200, BC90, BC95
VY-4	VX-821, VX-824, VX-829, VX-871, VX-874, VX-879 <b>Radio &amp; Battery or Battery Only:</b> VX-921, VX-924, VX-929, VX-971, VX-974, VX-979
VY-5	VX-354, VX-351 (FNB-V96Li) *VX230 Series (Multi-Bank V4 Charger Required) <b>Battery Models:</b> FNB-V103Li, FNB-V104Li
VY-6	VX-450, VX-451, VX-454, VX-459 <b>Battery Models:</b> FNB-V112Li, FNB-V113Li
VY-7	VX-231, VX-261, VX-264, VX-350, VX-450, EVX-530 Series. <b>Radio &amp; Batteries:</b> V127LI-UNI, V131LI-UNI, V133LI-UNI. <b>Battery Only:</b> V126LI-UNI, V128LI-UNI, V129LI-UNI, V130LI-UNI, V132LI-UNI, V134LI-UNI
VY-8	BC 250D
<b>Harris / M/A Com / Tyco</b>	
MA-7	Jaguar 700P, P5100 series, P5200 Series, P7100 Series, P7200 Series. <b>Unity XG-100P (Battery Only)</b>
MA-8	P7300, P5500, P5400, P5300, XG-25, and XG-75 <b>Battery Note:</b> Requires V4 Charger

## Questions About Our Charger Cups?

Contact us at **1-866-532-9005** | [sales@impactcomms.com](mailto:sales@impactcomms.com)

[ImpactComms.com](http://ImpactComms.com)

# Charger Cup Selection Chart



Impact Part Number	Radio Models
<b>Relm/Bendix King</b>	
KEN-1	RPV Series
RBK-1Li	E, G & L Series, DPH 9.6V Li-ion <b>Battery Note:</b> Requires V4 Charger
RBK-1Ni	E, G & L Series, DPH 9.6V Ni-Cd & Ni-MH <b>Battery Note:</b> Requires V4 Charger
RBK-2	KNG-P150/150T2, P400/400T2, P500/500T2, P800/800T2 <b>Battery Note:</b> Requires V4 Charger <b>Batteries Supported:</b> KAA0100-PW, KAA0100/IS <b>Batteries NOT SUPPORTED:</b> KAA0101, KAA0120
<b>Novel/Entel/Ritron</b>	
NOV-1	Novel NP-60, Entel HX series, Ritron SLX series
<b>ENTEL</b>	
ENT-2	Entel HT series
<b>EF Johnson</b>	
EFJ-4	EF Johnson 5100 series. Replaces EFJ-3. Supports latest Li-Ion battery models and all other chemistries 5100ES Series, 51 Fire ES, 51LT ES, 51SI ES Series, ASCEND ES Series, AN/PRC-127EFJ
EFJ-5	Viking VP600/900, FIRE
<b>Tait</b>	
TA-2	TP8100 and 9400 Series <b>Battery Note:</b> Requires V4 Charger
TA-3	TP7110 Series <b>Battery Note:</b> Requires V4 Charger
<b>HYT/Hytera</b>	
HYT-2	TC500-U1/U2, TC500-V1/V2, Blackbox
HYT-6	PD500, PD502, PD508, PD700, PD702, PD708, PD780, PD782, PD602

## Questions About Our Charger Cups?

Contact us at **1-866-532-9005** | [sales@impactcomms.com](mailto:sales@impactcomms.com)

[ImpactComms.com](http://ImpactComms.com)